PROJECT OUTCOME CERTIFICATE

	E	Sinking	3 Pastockion	a well at Bije co
Project code		& historico long of Sunatata (M)		
		Project o	omponents	
		to be filled	d in by PHEO;	
ntake (dia. & Cap. in MLD)		-NA-		
WTP (Cap. in MLD)		1-40 & 50 Lpm		
Production well				9.
Nos. & Cap. in ML)		-NA-		-
Storage ESR (Nos. & Cap. in ML) GSR (Nos. & Cap. in ML)		-NA-		
D	I IAIF)			
istribution network ength in Km)		1500 mps		
			tcome	
(Pri	e & post	target to be entered b	y PHEO in sync. with mon	toring tool)
Description	Pre Implementation		Post Implementation - Target	Post Implementation -Actual (to be verified & recorded by the team)
Increase in Supply Quantity (LPCD*)	_		135	100
Storage (ML)	- NA-		-NA-	-NA -
Increase in Supply Duration (Hrs)	_		1 hr	thr
Household Coverage In project area	(Enter Total no. of houses in the project area & existing connections if any)		(Enter 10 geted no. of New connections)	(Enter 25 to 1 no. of new Connections)
	Equity & Adequacy		Yes	Please Tick the
Equity & Adequacy	L	last house in tail end)	No	appropriate box
	reaches			
Equity & Adequacy (Adequate quantity I	eaches	· /	110	
(Adequate quantity i	1			
(Adequate quantity in *Computation of LPC	CD =(Dai	ily quantity supplied to	project area in ltr)/(total	population in project area)
(Adequate quantity in *Computation of LPC	CD =(Dai	ily quantity supplied to	project area in ltr)/(total	population in project area)
(Adequate quantity in *Computation of LPC	CD =(Dai	ily quantity supplied to	project area in ltr)/(total	
(Adequate quantity in *Computation of LPC Certified that the abo	CD =(Dai	ect has been completed wledge.	project area in ltr)/(total	population in project area)
*Computation of LPC Certified that the abo are correct to best of Signature, Name'& D	CD =(Dai ve proje our kno esignati	ity quantity supplied to each has been completed wiedge.	project area in ltr)/(total and put to service. The i	population in project area)
*Computation of LPC Entified that the about of correct to best of signature, Name & D	CD =(Dai eve proje our kno esignati	ect has been completed wiedge.	project area in ltr)/(total) and put to service. The i	population in project area)
*Computation of LPC Certified that the abo ere correct to best of Signature, Name & D Lupricabha Be	CD =(Dai eve proje our kno esignati	ect has been completed wiedge. on Executive fice. The First August Miners	and put to service. The i	nformation provided herein
*Computation of LPC Certified that the abo are correct to best of Signature, Name'& D	CD =(Dai eve proje our kno esignati	ect has been completed wiedge.	and put to service. The i	nformation provided herein