

PROJECT OUTCOME CERTIFICATE

Name of Project	"Replacement of damaged infiltration gallery in the river Khadkhai near existing Intake well for improvement of water supply to Ward No.3, 4, 5, 6, 7, 8, 11 & 12 of Rairangpur Municipality."		
Project code			
Project components (to be filled in by PHEO)			
Intake (dia. & Cap. In MLD)	—		
WTP (Cap. In MLD)	—		
Production well (Nos. & Cap. In ML)	—		
Storage ESR (Nos. & Cap. In ML) GSR (Nos. & Cap. In ML)	—		
Distribution network (length in km)	74 Mtr of 200 mm dia PVC perforated pipe as infiltration gallery.		
Outcome (Pre & post target to be entered by PHEO in sync. With monitoring tool)			
Description	Pre Implementation	Post Implementation- Target	Post Implementation- Actual (to be Verified & recorded by the team)
Increase in Supply Quantity (LPCD*)	96 LPCD	106 LPCD	
Storage(ML)	—	—	
Increase in Supply Duration(Hrs)	2.0 Hrs	3.5 Hrs	
Household coverage in project area	(Enter Total no. Of house in the project area & existing connections if any) N/A	(Enter Target no. Of New connection) 785 Nos	(Enter actual no. Of new connections) 94 Nos
Equity & Adequacy (Adequate quantity reaches last house in tail end)	Yes No		Please Tick the appropriate box

*Computation of LPCD = (daily quantity supplied to project area in ltr) / (total population in project area)

Certified that the above project has been completed and put to service. The information provided herein are correct to best of our knowledge.

Signature, Name & Designation

Councillor(s)/ Corporator (s)	Executive Officer's representative	Collector's Representative	PHEO Representative

Note: This certification cannot be treated as confirmation or approval of execution quantity.

Alkan
25/5/18
Junior Engineer
Rairangpur Municipality.

Ansuman partha
TL, DUDA
25/5/18

[Signature]
25/5/18
Senior Engineer
P.H. Section, Rairangpur

[Signature]
25.5.18
Chairperson
Rairangpur Municipality.